



Summa Four, Inc., 25 Sundial Avenue, Manchester, New Hampshire 03103

Technical Bulletin #: TM-C1-0158
Date Issued: October 7, 1997
Audience: Integrated SS7 Customers
Product(s) Affected: Integrated SS7 Systems
Distribution: ___ - Critical X - Standard ___ - Special

Purpose of Bulletin

The terminal attached to the SS7 SPARC serial port can cause an SS7 reboot/halt under certain failure conditions. This complication is in the Solaris (or SunOS) operating system, which hangs when the VT console is either powered down or has a power supply failure. The following workarounds can address this issue.

Corrective Action

If the VT terminal is either powered down or has a power supply failure, the serial port receives a signal that causes the processor to reboot/halt. You can address this issue with any of the following workarounds:

1. Disconnect the VT terminal(s) from the SPARC processor serial connection.
 - a. Reconnect for active use only.
- OR-
- b. Leave disconnected and perform all terminal functions via a Telnet session from the host or another connectivity device.

2. Apply a cable fix that uses a resistor between two pins of the serial cable—a 4.7k ohms, .25-watt resistor between pins 3 and 25. Then, reconnect the VT terminal.

CAUTION: This hardware solution is NOT officially supported by Sun.

